


EVC Drone Solutions



Severity overview




#	Severity	Components	Issues	Comments	Page
1	4		Vegetation		4
2	3	Structure/Wood/Cross Arm	Damage	cross arm brackets has a Crack	5
3	5	Insulator/Ceramic	Other Issue	Tirewire is Cross	6
4	2	Insulator	Broken		7
5	4		Broken		7



DJI_20240407123818_0001_V.JPG

Apr 7, 2024, 8:38:18 AM

 33.9643903, -84.0020044


313.4m above sea level
→ East (104.4°)


For a more detailed overview go to app.scopito.com/en-US/inspection/38970?image=18578078

1

 Severity 4

 Vegetation



 **Remedy Action:**
Vegetation need to be Trim



DJI_20240407124422_0021_V.JPG

Apr 7, 2024, 8:44:22 AM

📍 33.9644714, -84.0020701

308.4m above sea level

↘ Southeast (150.2°)

For a more detailed overview go to app.scopito.com/en-US/inspection/38970?image=18578088

2

🚩 Severity 3

⚠️ Damage

🏗️ Structure/Wood/Cross Arm



👤 **EV**
cross arm brackets has a Crack



DJI_20240407124501_0025_V.JPG

Apr 7, 2024, 8:45:01 AM

📍 33.9644733, -84.0020764

307.9m above sea level

↘ Southeast (155.1°)


For a more detailed overview go to app.scopito.com/en-US/inspection/38970?image=18578091

3


🔥 Severity 5

⚠️ Other Issue

🔧 Insulator/Ceramic



👤 **EV**
Tirewire is Cross



DJI_20240407124808_0034_V.JPG

Apr 7, 2024, 8:48:08 AM

📍 33.9643813, -84.0019152

308.8m above sea level

← West (286.4°)

For a more detailed overview go to app.scopito.com/en-US/inspection/38970?image=18578102

4

🔧 Severity 2

⚠️ Broken

🔌 Insulator



5

🔧 Severity 4

⚠️ Broken



Remedy Action:

Loose #6 copper from LA from road side